## **Borescope list 2025-1**

Great Britain BTPA Gator2 all turbines OK

Engines: xxx94C, xxx13E, xxx87T, xxx85A

Italy ATPI Vimana all turbines OK

Xxxxxx012

Aspirateur all turbines OK

Xxxxx081, xxxxx020, xxxxx067P1

Hot Iron all turbines ok

Xxxxxx100

France FTPF Redoutable all turbines OK Engines:

Xxxxxxxx037, xxxxxxxx285, xxxxxxx033, xxxxxx021

Rising Star all turbines OK

Engines: xxxxxxx022, xxxxxxx005, xxxxxxx016,

xxxxxxxx063

Germany DTTO Erlkonig all turbines OK

Engines: xxxxx295, xxxxx455, xxxxx346, xxxxx069P1, xxxxx116P1

Iwan all turbines OK

Engines, xxxxxx005, xxxxxx071, xxxxxx069

Netherlands NTTO The Hind all turbines OK

Engine: xxxxxx115

Burning Madness all turbines OK xxxxx336, Cxxxxx113, Cxxxxx398

Russian Roulette a ll turbines OK Engines: xxxxxx093, xxxxxxx178

Whispering Giant all turbines OK

Engines:xxxxxxx002, xxxxxxx002, xxxxxxx001,

Xxxxxxx144, xxxxxxx072

Belgium BVP Smoking Barrels all turbines OK

Engines: xxxxxx62, xxxxxx84

On the above-OK.mentioned turbine-engines a borescopic inspection is carried out to view the condition of the combustion chamber, and the turbines. During this inspection no cracks / overheating (blade tips) of turbine wheels are found and no significant burn or disortions of nozzle-guide-vanes are found. The ETPC turbine tech team emphasizes that this boroscopic inspection is only additional to the normal engine inspections and only a moment view. No expressed or implied warranty of safety is intended nor may be inferred from this inspection.

On behalf of the ETPC turbine tech team, 05-06-2025, Willem Wempe

## **Borescope list 2025-1**